

ATT:

LOADING CREDIT FOR MODEL ECOMAIL (DIGITAL MACHINES)

To load credit please follow the under-mentioned steps:

1. Switch the machine on.
The following screen will appear:

ACCOUNT:		TOTAL:	
PASSWORD:		PIECES:	
SUB-ACCOUNT:		0 - PIECES	
		CREDIT:	
		LOADED:	
1	2	3	0
4	5	6	OK
7	8	9	CE

2. Enter your highest Account, usually Account No. 2 (The same Account that you normally use when loading credit.) AND put in password for account.... Press OK
3. On the following screen, press on the button INFO/SETUP 1.
4. Next screen, press on button INFO/SETUP 2.
5. Next screen, press on button INFO/SETUP 3.
6. Next screen, press on button LOAD CREDIT.
7. Screen changes and you will see the RETURN CODE. Fill on the FRAMALINK REMOTE METER RESET REQUEST FORM and fax to Johannesburg on Fax No: (011) 463-1006.
8. When you receive the RESET CODE from Frama just type it in on the same screen and the machine will be automatically re-credited.